

United States of America
Department of Transportation Federal Aviation Administration
Supplemental Type Certificate

Number SP952NW

This certificate, issued to: Pacific Propeller International LLC
5802 South 228th Street
Kent, WA 98032-1810

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 35 of the Federal Aviation Regulations, dated January 1, 1973.

Original Product—Type Certificate Number: P-736-8
Make: Hamilton Standard
Model: 22D30 and 22D40

Description of the Type Design Change: Installation of Pacific Propeller, Inc. Extension Shaft-Assembly P/N PPI-7014-1 and Piston Assembly P/N PPI-7018 in the HSP-22D30 Hub Assembly and P/N 7017-1 Extension Shaft Assembly and Piston Assembly PPI-7018 in the HSP-22D40 Hub Assembly per Pacific Propeller Drawing List No. 76020, dated June 5, 1980, or later FAA Sealed Revision thereto.

Limitations and Conditions: This approval should not be extended to other propellers of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that propeller.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 14, 1977

Date reissued: March 25, 2004

Date of issuance: June 19, 1980

Date amended: March 25, 2004



By direction of the Administrator

(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.